

RECENT FLOODING PICTURES TAKEN LAND NORTH OF BRACKEN WAY

1. The following photos were taken on the 7th December 2015
Site: AS.06 EXTENSION TO SITE SR4.11



2. The following photos were taken on the 1st December 2015 of Site SR4.11



RECENT FLOODING PICTURES TAKEN OF SITE MN2.49 AND ADJOINING SITE

1. The following photos were taken on the 4th December 2015 and are the site adjoining MN2.49



2. The following photos were taken on the 7th December 2015 of Site MN2.49





3. The following photos were taken on the 6th December 2015 and clearly show the ditches full to capacity on the existing site and leading away from the sites. They also show the ditches overflowing onto the land.



RECENT FLOODING PICTURES TAKEN LIVERPOOL RD SITE – MN2.16

1. The following photos were taken on the 7th November 2015



2. The following photos were taken the 10th November 2015





3. The following photos were taken the 19th November 2015



4. The following photos were taken the 4th December 2015





5. The following photos were taken the 5th December 2015





RECENT FLOODING PICTURES TAKEN IN AND AROUND FORMBY

1. The following photos were taken of Park Close, looking down from Park Road junction in the morning on the 19th November 2015 and shows both Park Close and Park Road flooded.



2. The following photos were taken in Park Close on the 19th November 2015 lunchtime by residents in Park Close on mobile phone



3. Pictures taken of Park Close and junction of Park Close/Park Road on the 19th November late afternoon



4. Pictures taken of Park Close and junction of Park Close/Park Road on the 3rd December approximately 9.30 pm



5. Picture taken of Church Road on the 3rd December approximately 9.30 pm



6. Picture taken of Ravenmeols Road on the 5th December 2015



7. Pictures taken of Altcar Lane on the 5 December 2015.



8. Pictures taken of Duke Street on the 5 December 2015.



9. Pictures taken of Queens Road on the 3rd December by Formby Bubble and posted on their Website.



